State of California AIR RESOURCES BOARD

EXECUTIVE ORDER D-353-43

Relating to Exemptions under Section 27156 and 38391 of the Vehicle Code

Miller Catalyzer Corporation "Series 31000 Three-way Catalytic Converters"

WHEREAS, Vehicle Code Sections 27156 and 38395, and Title 13, California Code of Regulations (hereafter "CCR") Section 2222(h), authorize the California Air Resources Board and its Executive Officer to exempt new aftermarket catalytic converters from the prohibitions of Vehicle Code Section 27156 and 38391.

WHEREAS, Miller Catalyzer Corporation of 3295 Depot Road, Hayward, California 94545, has applied to the Air Resources Board for exemption from the prohibitions in Vehicle Code Sections 27156 and 38391 to market its new aftermarket Series 31000 three-way catalytic converters (TWC) on selected 1995 through 2003 model year General Motors light-duty trucks 2 (LDT2) and medium-duty vehicles equipped with on-board diagnostic II (OBD-II) systems as specified in Appendix D-353-43 and incorporated herein. Series 31000 TWC will be used for single catalytic converter application (one unit) and may be sold as universal or direct fit system.

WHEREAS, pursuant to the authority vested in the Executive Officer by Health and Safety Code Section 39515 and in the Chief, Mobile Source Operations Division by Health and Safety Code Section 39516 and Executive Order G-02-003, the Air Resources Board finds that the above aftermarket catalytic converters comply with the California Vehicle Code Sections 27156 and 38395 and Title 13, California Code of Regulations, Section 2222(h). Emission performance of the catalytic converter was based on durability bench-aging by Umicore Automotive Catalysts using the Air Resources Board-modified RAT-A bench-aging cycle for 100 hours as specified in Appendix A to the "California Evaluation Procedures for New Aftermarket Catalytic Converters" as adopted on October 25, 2007.

WHEREAS, previous emissions and OBD II compatibility tests conducted by Miller Catalyzer Corporation using a vehicle of weight classification and exhaust configuration similar to those listed in Appendix D-353-43 and certified to Low Emission Vehicle (LEV) standards resulted in the issuance of Executive Orders D-353-13, it was determined that the installation of Series 31000 on the vehicles listed in Appendix D-353-43 meets the requirements of California regulation for aftermarket catalytic converters.

THEREFORE, IT IS HEREBY RESOLVED that Miller Catalyzer Corporation's 31000 TWCs are exempted from the prohibitions in Vehicle Code Sections 27156 and 38391 for installation on the approved vehicle applications specified in Appendix D-353-43 subject to the following conditions:

- 1. No changes are permitted to the catalytic converters as described in the application for exemption. Any changes to the catalytic converters or any of their components, and other factors addressed in this order must be evaluated and approved by the Air Resources Board prior to marketing in California.
- 2. Marketing of the catalytic converters using identifications other than those shown in the exemption application, and in this Executive Order, or marketing of the catalytic converters for application other than the ones shown in this Executive Order shall be prohibited unless prior approval is obtained from the Air Resources Board. Exemption of these products shall not be construed as an exemption to sell, offer for sale, or advertise any components of the catalytic converters as individual devices.
- 3. Any oral or written references to this Executive Order or its content by Miller Catalyzer Corporation, its principals, agents, employees, distributors, dealers, or other representatives must include the disclaimer that the Executive Order or the exemption it provides is not an endorsement or approval of any emission reduction claims for the catalytic converters and is only a finding that the catalytic converters are exempt from the prohibitions of Vehicle Code Sections 27156 and 38391.
- 4. Miller Catalyzer Corporation's installation instructions for the new catalytic converters must conform to requirements in Section (h) of the "California Evaluation Procedures for New Aftermarket Catalytic Converters," as adopted October 25, 2007.
- 5. Installation of the catalytic converters shall not cause the relocation of an oxygen sensor. Oxygen sensors must be installed in the same location, position and orientation as prescribed in the original equipment manufacturer's configurations.
- 6. Upon installation, the catalytic converters must carry a manufacturer's warranty for five (5) years or 50,000 miles as prescribed in Section (f)(2) of the "California Evaluation Procedures for New Aftermarket Catalytic Converters," as adopted October 25, 2007.
- 7. Miller Catalyzer Corporation and its vendors may not advertise the new aftermarket catalytic converters as "high flow or easy flow" catalytic converters or use any phrase that could make them appear to perform better than the original equipment manufacturer (OEM) catalytic converters.
- 8. Any marketing arrangement of the new aftermarket catalytic converter by a third party, which involves the use of packaging identification different from the ones described in this Executive Order, must be approved by the Air Resources Board prior to shipment.
- 9. Miller Catalyzer Corporation, its associates, vendors, other businesses and individuals associated with Miller Catalyzer Corporation may not sell or supply new aftermarket catalytic converter substrates to a third party to be assembled in a different facility and marketed under this Executive Order without approval from the Air Resources Board.

- 10. Miller Catalyzer Corporation shall comply with the quality control procedures and reporting requirements in Section (f)(5) of the "California Evaluation Procedures for New Aftermarket Catalytic Converters," as adopted October 25, 2007.
- 11. Quality control reports must be submitted on a quarterly basis and warranty information reports on a semi-annual basis, starting with periods covering January 1 through March 31, 2009 and January 1 through June 30, 2009, respectively.
- 12. Miller Catalyzer Corporation must provide a permanent label or stamp as specified under Section (f)(1) of the "California Evaluation Procedures for New Aftermarket Catalytic Converters," as adopted on October 25, 2007.
- 13. Miller Catalyzer Corporation's vehicle application catalog must conform with the requirements specified under Section (f)(4) of the "California Evaluation Procedures for New Aftermarket Catalytic Converters," as adopted on October 25, 2007.

Executive Order D-353-21 dated February 22, 2008, is hereby superseded and of no further force and effect.

Violation of any of the above conditions shall be grounds for revocation of this order. The order may be revoked only after a 30-day written notice of intention to revoke it, during which period the holder of the order may request in writing a hearing to contest the proposed revocation. If a hearing is requested, it shall be held within 30 days of receipt of the request, and the order may not be revoked until a determination is made, after the hearing, that grounds for revocation exist.

Mobile Source Operations Division

Executed at El Monte, California, this day of December 2008.

MILLER CATALYZER CORPORATION - CATALYTIC CONVERTER - D-353-43

| | _ | Miller Catalyze | r Corpo | artion, Catalytic (| Converter Sei | ies 3100 | 0, for GN | M MDV and | l LDT2 | | | |
|-----|---------------|--------------------------------------|----------------|---|------------------------|-----------------|-----------------|---------------------|-------------------|-----------|-----------|------------------|
| No. | Model Year | Vehicle Model | Engine Size | Engine Family | Certification Level | Weight Class | Exhaust Type | Total Converters | Converter Type | Monitored | Universal | Direct Fit |
| | | Chevrolet S10 Pickup | | | _ | | | | | | | 31061 |
| | | Chevrolet S10 Blazer | | | | LDT2 | | | | | | 31061 |
| 1 | | GMC S15 Pickup | | TGM4.32PGKEK | | | | | | | | 31064 |
| | | GMC S15 Jimmy | | | | | | | | | | 31064 |
| | | Oldsmobile Bravada | | | | | | | | | | 31064 |
| | | Chevrolet Van 2WD, GMC Savana 2WD | | | | | | | | | | 31058B |
| 2 | | Chevrolet Astro, K1500 PU 2WD & 4WD | 1 | TGM4.35PGFEK | | MDV2 | | | | | | 31058B |
| | | GMC Safari, K1500 Sierra 2WD &4WD | 4.3L | | | | | | | | | 31058B |
| 3 | | Chevrolet Astro | | TGM4.32PGKEL | | LDT2 | | | | | | 31058B |
| - | | GMC Safari Chevrolet/GMC 1500 Pickup | | | | | - | | | | | 31058B 31058B |
| | | Chevrolet/GMC 2500 Pickup | | TGM4.38PGBEK | | | ı | | | | | 31058B |
| 4 | | Chevrolet/GMC G1500 Van | | | | MDV3 | | · | | | | 31058B |
| " | | Chevrolet/GMC G2500 Van | | | | IVID V3 | | · | | | 01010 | 31058B |
| | | Chevrolet/GMC G3500 Van | | | Tier 1 | | S | 1 | TWC | 1 | 31212 | 31058B |
| | | Chevrolet/GMC 1500 Pickup 2WD | _ | | 1 | | 2 | | | | | 31068 |
| | | Chevrolet/GMC 2500 Pickup 2WD | 1 | | | MDV2 | | | | | | 31068 |
| 5 | | Chevrolet/GMC G1500 Van | 1 1 | TGM5.0HPG1EK | | | | | | | | 31008 |
| | | Chevrolet/GMC G2500 Van | 5.0L | | | | | | | | | 31071 |
| | | Chevrolet/GMC 1500 Pickup 4WD | 1 | | 1 | | | | | | | 31068 |
| 6 | | Chevrolet/GMC 2500 Pickup 4WD | 1 | TGM5.0JPG1EK | | MDV3 | | | | | | 31068 |
| | | Chevrolet/GMC G3500 Van | 1 | 101111111111111111111111111111111111111 | | 1.12 | | | | | | 31068 |
| | | Chevrolet S10 Pickup | 4.3L | | 1 | | | | | | | 31061 |
| | | Chevrolet S10 Blazer | | | | | | | | | | 31061 |
| 7 | 1997 | GMC S15 Pickup | | VGM4.32PG1EK | | LDT2 | | | | | | 31064 |
| | | GMC S15 Jimmy | 1 - | | | | | | | | | 31064 |
| | | Oldsmobile Bravada | | | | 1 | | | | | | 31064 |

| | | Miller Catalyzer Corpoa | rtion, Cat | alytic Converter S | eries 31000, (| GM Med | lium Dut | y Trucks, U | p to 14,000 | ALVW | | |
|-----|---------------|-------------------------------|----------------|--------------------|------------------------|-----------------|-----------------|---------------------|-------------------|-----------|-----------|------------|
| No. | Model Year | Vehicle Model | Engine Size | Engine Family | Certification Level | Weight Class | Exhaust Type | Total Converters | Converter Type | Monitored | Universal | Direct Fit |
| 8 | | Chevrolet Astro | | VGM4.32PG2EK | TLEV | LDT2 | | | | | | 31059B |
| ° | | GMC Safari | | VOIVI4.321 OZEK | ILEV | LD12 | | | | | | 31059B |
| | | Chevrolet/GMC 1500 Pickup | | | | | | | | | | 31058B |
| 9 | | Chevrolet/GMC 2500 Pickup | | VGM4.3HPG1EK | Tier 1 | | | - | | | | 31058B |
| 9 | | Chevrolet/GMC G1500 Van | 4.3L | VOM4.5HFGIEK | 1161 1 | MDV2 | | | | | | 31058B |
| | | Chevrolet/GMC G2500 Van | | | | MID V2 | - | | | | | 31058B |
| 10 | | Chevrolet Astro | | VGM4.3HPG3EK | LEV | | | | | | | 31058B |
| 10 | 1997 | GMC Safari | | VOM4.5HFU3EK | LEV | | | | | | | 31058B |
| 11 | 1997 | Chevrolet/GMC G3500 Van | | VGM4.3JPG1EK | | MDV3 | | | | | | 31058B |
| | | Chevrolet/GMC 1500 Pickup 2WD | | | Tier 1 | | | | | | | 31068 |
| 12 | | Chevrolet/GMC 2500 Pickup 2WD | | VGM5.0HPG1EK | | MDV2 | | | | | | 31068 |
| 12 | | Chevrolet/GMC G1500 Van | | | | | | | | | | 31071 |
| | | Chevrolet/GMC G2500 Van | 5.0L | | 1161 1 | | | | | | | 31071 |
| | | Chevrolet/GMC 1500 Pickup 4WD | | VGM5.0JPG1EK | | MDV3 | S | 1 | TWC | 1 | 31212 | 31068 |
| 13 | | Chevrolet/GMC 2500 Pickup 4WD | | | | | | | | | | 31068 |
| | | Chevrolet/GMC G3500 Van | | | | | | | | | | 31068 |
| 14 | | Chevrolet Astro | | WGMXA04.3188 | LEV | MDV2 | | | | | | 31066 |
| 14 | | GMC Safari | | W GIVLX A04.5188 | LEV | MID V2 | | | : | | | 31066 |
| 15 | | Chevrolet Astro | | WGMXT04.3187 | TLEV | LDT2 | | | | | | 31067 |
| 13 | | GMC Safari | | W ONLX 104.3187 | ILEV | LD12 | | | | | | 31067 |
| 16 | | Chevrolet/GMC 1500 Pickup | | WGMXA04.3190 | | MDV2 | | | | | | 31067 |
| 10 | 1998 | Chevrolet/GMC 1500 Pickup | 4.3L | WGWIXA04.3190 | | IVID V Z | | | | | | 31067 |
| | | Chevrolet S10 Pickup | | | | | | | | | | 31090 |
| | | Chevrolet S10 Blazer | | | Tier 1 | | | | | | | 31090 |
| 17 | | GMC S15 Pickup | | WGMXT04.3184 | | LDT2 | | | | | | 31058B |
| | | GMC S15 Jimmy | | | | | | | | ļ | | 31058B |
| | | Oldsmobile Bravada | | · . | | | | | | | | 31058B |

| | | Miller Catalyzer Corpoa | rtion, Cata | alytic Converter S | eries 31000, (| GM Med | lium Dut | y Trucks, U | p to 14,000 | 0 ALVW | | |
|-----|-------|---------------------------|----------------|------------------------------|----------------|-----------|----------|-------------|-------------|-----------|-----------|------------|
| No. | Model | Vehicle Model | Engine Size | Engine Family | Certification | | | Total | Converter | Monitored | Universal | Direct Fit |
| | Year | Chevrolet S10 Pickup | Size | | Level | Class | Type | Converters | Туре | | | 31061 |
| 18 | | Chevrolet S10 Blazer | \dashv | WGMXT04.3182 | | MDV2 | | | | | | 31061 |
| | | Chevrolet/GMC G1500 Van | 4.3L | | | | | Į. | | | | 31058B |
| 19 | | Chevrolet/GMC G2500 Van | | WGMXT04.3192 | | MDV3 | | | | | | 31058B |
| | | Chevrolet/GMC G3500 Van | | | | | | | | | | 31058B |
| | 1998 | Chevrolet/GMC 1500 Pickup | | | Tier 1 | | | | | | 31212 | 31059B |
| 20 | | Chevrolet/GMC 2500 Pickup | | WCMWADE 0100 | · | MDV2 | _ | | | | | 31059B |
| 20 | | Chevrolet/GMC G1500 Van | 5.0L | WGMXA05.0182 | | | | | | | | 31071 |
| | | Chevrolet/GMC G2500 Van | 3.0L | | | | | | | | | 31071 |
| 21 | | Chevrolet/GMC 1500 Pickup | | WGMXA05.0184 | | | | | | | | 31059B |
| 21 | | Chevrolet/GMC 2500 Pickup | | | | MID V3 | | | | | | 31059B |
| 22 | | Chevrolet Astro | | XGMXT04.3187 XGMXA04.3188 | TLEV | LDT2 | | 1 | , | | | 31058B |
| 22 | | GMC Safari | | | | LD12 | - " | | TWC | 1 | | 31058B |
| 23 | | Chevrolet Astro | | | | MDV2 | | | | | | 31059B |
| 23 | | GMC Safari | 4.3L | AUIVIAA04.5188 | | WII) V 2 | | | | | | 31059B |
| 24 | | Chev/GMC G1500 Van | | XGMXA04.3190 | | MDV2 | | | | | | 31058B |
| 24 | | Chev/GMC G2500 Van | | AGIVIAA04.5190 | | 10117 (2 | | | | | | 31058B |
| 25 | 1999 | Chevrolet/GMC G3500 Van | | XGMXA04.3192 | | MDV3 | | | | | | 31069 |
| | 1999 | Chevrolet/GMC 1500 Pickup | | | | | | | | | | 31058B |
| 26 | | Chevrolet/GMC 2500 Pickup | | XGMXA05,0182 | Tier 1 | MDV2 | | | | | 31058B | |
| 20 | | Chevrolet/GMC G1500 Van | | AGIVIAAU3.0182 | 1161 1 | 10117 0 2 | | | | | | 31069 |
| | | Chevrolet/GMC G2500 Van | 5.0L | _ | | | | | | | | 31069 |
| | | Chevrolet/GMC 1500 Pickup | | | | | | | | * | | 31058B |
| 27 | | Chevrolet/GMC 2500 Pickup | | XGMXA05.0184 | | MDV3 | | | | | | 31058B |
| | | Chevrolet/GMC G3500 Van | | | | | | | | | | 31069 |

| | Miller Catalyzer Corpoartion, Catalytic Converter Series 31000, GM Medium Duty Trucks, Up to 14,000 ALVW | | | | | | | | | | | |
|-----|--|--------------------------|----------------|----------------|------------------------|-----------------|-----------------|---------------------|-------------------|-----------|-----------|------------|
| No. | Model Year | Vehicle Model | Engine Size | Engine Family | Certification Level | Weight Class | Exhaust Type | Total Converters | Converter Type | Monitored | Universal | Direct Fit |
| 28 | | Chevrolet/GMC G2500 Van | | YGMXT05.7188 | Tier 1 | MDV2 | | | | | | 31058B |
| 26 | 2000 | Chevrolet/GMC G3500 Van | 5.0L | | | WID V2 | | | | | | 31058B |
| 29 | 2000 | Chevrolet G1500/2500 Van | 3.0L | YGMXT05.7189 | | MDV3 | | | | | | 31060B |
| 29 | | GMC G1500/2500 Savana | | | | | | | | | | 31060B |
| 30 | | Chevrolet/GMC G1500 Van | 4.3L | 1GMXA04.3192 | LEV | MDV2 | S | 1 T | TWC | 1 | 31212 | 31058B |
| | | Chevrolet/GMC G2500 Van | | | | | | | | | | 31058B |
| 31 | 2001 | Chevrolet/GMC G1500 Van | | 1GMXA05.0181 | | | | | | | | 31058B |
| 31 | | Chevrolet/GMC G2500 Van | 5.0L | 1010LXA03.0161 | Tier 1 | | | | | | | 31058B |
| 32 | | Chevrolet/GMC G3500 Van | | 1GMXA05.0182 | | | | | | | | 31058B |

Additional Vehicles 1

| | | Miller Catalyzer Corpoarti | on, Cata | alytic Converter S | eries 31000, (| GM Med | lium Dut | y Trucks, U | p to 14,000 | ALVW | | |
|-----|---------------|---|----------------|--------------------|------------------------|-----------------|-----------------|---------------------|-------------------|-----------|-----------|------------|
| No. | Model Year | Vehicle Model | Engine Size | Engine Family | Certification Level | Weight Class | Exhaust Type | Total Converters | Converter Type | Monitored | Universal | Direct Fit |
| 33 | 1995 | S-10 Blazer/Jimmy | 4.3L | S3G4.329GFGJ | Tier 1 | LDT2 | | 1 | TWC | 1 | 31212 | |
| 33 | 1993 | S-10 Pickup, Sonoma | 4.JL | | | | | | | | | |
| 34 | 1996 | Lumina MV, Silhouette, Transport | 3.4L | TGM3.428GFEK | | LDIZ | | | | | | |
| 35 | 1997 | Venture, Transport, Silhouette |] 3.4L | VGM3.428G2EK | TLEV | | | | | | | |
| 36 | 1998 | G1500/2500 Van | 4.3L | WGMXA04.3192 | Tier 1 | MDV3 | | | | | | |
| 37 | 1996 | Venture, Transport, Silhouette | | WGMXT03.4142 | TLEV | | ~ | | | | | |
| 38 | 1999 | Venture, Transport, Silhouette | 3.4L | XGMXT03.4142 | ILEV | LDT2 | S | | | | | TBD |
| 39 | 2000 | Venture, Montana, Silhouette | | YGMXT03.4142 | | | | | | | | |
| 40 | | Chevrolet Trailblazer EXT GMC Envoy XL | | 2GMXA04.2187 | | MDV2 | | | | | | |
| | 2002 | Chevrolet Trailblazer 2WD/4WD | 4.2L | | LEV | LDT2 | | | | | | |
| 41 | | Oldsmobile Bravada 2WD/4WD | | 2GMXT04.2185 | | | | | | | | |
| | | GMC Envoy 2WD/4WD | | | | | | | | | | |

| | | Miller Catalyzer Corpoartio | on, Cata | llytic Converter S | eries 31000, (| GM Med | lium Dut | y Trucks, U | p to 14,000 | O ALVW | | |
|-----|---------------|--|----------------|--------------------|------------------------|-----------------|-----------------|---------------------|-------------------|-----------|-----------|------------|
| No. | Model Year | Vehicle Model | Engine Size | Engine Family | Certification Level | Weight Class | Exhaust Type | Total Converters | Converter Type | Monitored | Universal | Direct Fit |
| | | Chevrolet G1500/2500 Express 2WD | 4.3L | | | MDV2 | | | | | | |
| | | Chevrolet G1500/2500 Van 2WD | | | | | | | | | | |
| 42 | 2002 | GMC G1500/2500 Savanna Cargo 2WD | | 2GMXA04.3192 | LEV | | | | | | | |
| | 2002 | GMC G1500/2500 Savanna Passenger 2WD | | | | | | | | · | | |
| 43 | | G1500/2500 VAN | 5.0L | 2GMXT05.0181 | Tier 1 | | · | 1 | | | | |
| 44 | | G1500/2500 VAN | 5.02 | 2GMXT05.0182 | 7101 1 | MDV3 | | | | | | |
| | | CHEVROLET Trailblazer | 4.2L | 3GMXT04.2185 | | | | | | | | |
| 45 | | GMC Envoy | | | | LDT2 | | | | | | |
| " | | Oldsmobile Bravada | | | LEV | 2212 | | | | | | |
| | | Isuzu Ascender | | | | | S | 1 | TWC | 1 | 31212 | TBD |
| | | CHEVROLET Express 1500 2WD | | | | | | | | | | |
| | | CHEVROLET Express 2500 2WD | | | | | | | | | | |
| | 2003 | CHEVROLET Silverado 1500 2WD, 4WD | | | | | | | | | | |
| 16 | | CHEVROLET Van 1500 2WD | | 200 07704 2104 | |) (DV) | • | | | | | |
| 46 | | CHEVROLET Van 2500 2WD | 4.3L | 3GMXT04.3184 | | MDV2 | | | | | | |
| | | GMC Savana 1500 2WD | | | | | | | | | | |
| | | GMC Savana 2500 2WD | | | | | | | | | | |
| | | GMC Sierra 1500 2WD, 4WD | | | | | | | | | | |
| 47 | | Rendezvous, Venture, Silhouette, Aztec, Montana | 3.4L | 3GMXT03.4141 | | LDT2 | | | | | | |